







Remains of existing cover.
Flutes are 2.25 ins wide.
Shows cheap add on repair
made in 1950s to recover de-
spite loss of rear portion of
the original cover through
water damage.



Dickey seat back. Not
sprung. Set into curved
plywood board. Original
cover (under later one)
seems not to have been
fluted. The under colour
here may be closest to
original .

4.5"
deep

21.5"

39"